

# Village Maintenance Report

**To:** Mayor David Miller

**CC:** Deputy Mayor Larry Chaleff and Village Trustees

**From:** Brian Gauger, Motor Equipment Operator

**Date:** October 5, 2021

**Re:** September Maintenance Report

---

- Equipment Maintenance:** The right-side rear dirt shoe was replaced due to wear, and the right side rear main broom piston was replaced due to a leaking seal. The crew has been working on the John Deere cab doors (rusting), they are cutting the bad metal off and replacing and painting. The Ford driver's door window track was broken, we took the door apart to find the actual door metal to have cracked. We welded the door and track and re-installed. The 2003 International truck had an electrical problem with the rear taillight. After tracing the wire, we found multiple electrical wire failures and cut out bad sections and replaced wires.
- Tennis Courts:** After the heavy rainstorm, we found that the drainage field area behind the tennis courts sunk. We brought in roughly 15-18 yards of topsoil to fill the area. We rented a flat plate tamper to compact the soil and graded and seeded. The courts are checked daily, and leaves are being cleared as needed.
- General Maintenance:** Curb restoration was continuing throughout the village. We cleared the wood chips from grinding the stumps at 238 Clent Rd. & 10 Darley Rd, filled the holes with topsoil and seeded. We replaced a street light pole and fixture at 26 Linford Rd. that was broken due to the pole falling and hitting the ground. A new pole was installed. We were able to rebuild the fixture with spare parts and retrofit it to a LED bulb.